


Residual current circuit breaker with overcurrent protection (RCBO) Compliant with AS/NZS 61009.1





PLEASE NOTE

- The installation, maintenance and eventual replacement of this device must only be carried out by a qualified electrician.
- This device must not be repaired.
- All applicable local, regional and national regulations must be complied with during the installation, use, maintenance and replacement of this device.
- This device should not be installed if, when unpacking it, you observe that it is damaged.
- Schneider Electric cannot be held responsible in the event of noncompliance with the instructions in this document and in the documents to which it refers.
- The service instruction must be observed throughout the life time of this device.

Clip for DIN rail mounting Connection terminals Test button VISI-TRIP: Earth leakage fault tripping VISI-TRIP: Short-circuit and overload fault tripping VISI-SAFE: Positive contact indication


Installation


A A DANGER


HAZARD OF ELECTRIC SHOCK, EXPLOSION OR ARC FLASH

- Turn off all power supplying this device before working on it.
- Use a voltage tester with a suitable rated voltage, in order to check that all active conductors aren't energized.


Failure to follow these instructions will result in death or serious injury.









14 mm	116 mm ²	110 mm ²
G c		8
2 N.m	5.5 mm	PZ2







Clipsal by Schneider Electric (Australia) Pty Ltd

33-37 Port Wakefield Road Gepps Cross South Australia 5094

Customer Care Centre Tel: 1300 369 233 Email: customercare.au@se.com Fax: 1300 369 288

Fax: 1300 369 288 www.clipsal.com
JYT3788400-00